## Marin Resource Recovery Center

CONSERVATION - OUR EARTH, OUR MISSION, OUR JOB



11 January 2019

RE:

MARIN RESOURCE RECOVERY CENTER RECYCLING CERTIFICATION

To Whom It May Concern:

The Marin Resource Recovery Center (MRRC), in San Rafael, California, is a Material Recovery Facility that accepts mixed construction and demolition loads, as well as many other types of materials. All incoming loads are sorted and processed to remove recyclable materials.

MRRC provides quarterly reports to the Marin County Hazardous and Solid Waste Joint Powers Authority that are used by that agency for state reporting requirements. Attached is the most recent submission for the 4th quarter of 2018.

- 62,913 tons were received by the facility during the quarter.
- 40,223 tons were removed from the waste stream and recycled.

• 22,690 tons were landfilled.

This equates to a recycling rate of 63.9%.

Sincerely,

Charlie Wicke

Director, Financial Reporting

Marin Sanitary Service

(415) 456-2601



## MATERIAL RECOVERY FACILITY FORM

YEAR <u>2018</u>	REPÓRTIN	NG PERIOD	Reporting Quarter: (ple Jan - March April - June July - Sept Oct - Dec	X
1.) Company Name:	Marin Resource Recovery Center			
2.) Address:	1050 Andersen Drive San Rafael, Californi	a 94901		
	P.O. Box 10067 San Rafael, California 949 from above)	912		
4.) Telephone:	415-456-2601			
5.) Fax:	415-456-7595			
6.) Modem:				
7.) Contact Person :	Charlie Wicke			
Total tons of alternative daily cover (ADC) delivered to landfill in quarter:				_tons
9.) Total tons of greet this quarter.	waste delivered to composting facility(ies)		6,952	tons
10.) Total tons delivered to landfill(s) for disposal in quarter thru transfer station:			22,690	_tons
11.) Total tons delivered to Biomass facility(ies)for transformation in quarter: 8,43			tons	
12.) Total Tons Recovered:			24,834	tons_
13.) Total Tons Received:			62,913	tons
14.) Check the surve  Standard  Continuou  15.) Dates the survey	ized Weeks	Alternative Week Other (attach exp		
•	sed to allocate tonnage to jurisdiction (check % Received Other (attach explanation)	k only one):	% Landfilled (corrected for salvage	)