

July 18, 2025

RE: MARIN RESOURCE RECOVERY CENTER

**Q2 2025 RECYCLING CERTIFICATION** 

To Whom It May Concern:

The Marin Resource Recovery Center (MRRC), in San Rafael, California, is a material recovery facility that accepts mixed construction and demolition loads, as well as many other types of materials. All incoming loads are sorted and processed to remove recyclable materials.

MRRC provides quarterly reports to the Marin County Hazardous and Solid Waste Joint Powers Authority that are used by that agency for state reporting requirements. Attached is the most recent submission for the  $2^{nd}$  quarter of 2025.

- 97,780 tons were received by the facility during the quarter.
- 65,854 tons were removed from the waste stream and diverted.
- 31,926 tons were landfilled.

This equates to a diversion rate of 67.35% with ADC and a diversion rate of 67.35% without ADC.

Sincerely,

Ryan De Vera

Manager, Financial Reporting Marin Sanitary Service

(415) 456-2601

YEAR	<u>2025</u>	REPORTING PERIOD				
					Reporting Quarter : (ple Jan - March April - June	ease check)
					July - Sept Oct - Dec	
1.) Comp	oany Name:	Marin Resource Recovery Center	<u>er</u>			
2.) Addre	ess:	1050 Andersen Drive San Rafael, California 94901				
	ng Address: erent from ab	P.O. Box 10067 San Rafael, Ca pove)	lifornia 94912			
4.) Telep	hone:	<u>415-456-2601</u>				
5.) Fax:		<u>415-456-7595</u>				
6.) Mode	em:					
7.) Conta	act Person:	Ryan De Vera				
8.) Total tons of alternative daily cover (ADC) delivered to landfill in quarter:						_tons
<ol> <li>Total tons of green waste delivered to composting facility(ies) this quarter.</li> </ol>					7,966	_tons
10.) Total tons delivered to landfill(s) for disposal in quarter thru transfer station:					31,926	_tons
		red to Biomass facility(ies) for				
transformation in quarter:					10,720	_tons
12.) Total Tons Recovered:					47,168	_tons
13.) Total Tons Received:					97,780	_tons
14.) Check the survey type that was used:  Standardized Weeks  Continuous				Alternative Weeks		
15.) Date	— es the survey	was conducted:		•		
•		sed to allocate tonnage to jurisdic _% Received _Other (attach explanation)	tion (check only o	one):	% Landfilled (corrected for salvage)	_